


PENDANT JUNCTION BOX



- 1) Fasten the 4-Inch Crossbar to the Junction Box using #8-32 screws.
- 2) Run the fixture cable through the strain relief, Junction Box Canopy Cover/Plate, and 4-Inch Crossbar.
- 3) Have a certified electrician connect the power and control wires using appropriate wire-couplers.
- 4) Push up the Junction Box Canopy Cover/Plate and tighten the strain relief to the 4-Inch Crossbar.
- 5) Tighten the set screw on the strain relief to secure the fixture cable.

Wire Chart / Tableau des Fils	
White/Blanc	N
Black/Noir	L
Green/Vert	PG